



Scanvec Amiable - PROFILE READ ME

Important: Please make sure the following criteria are met for optima color fastness. Room humidity should be kept above 30% and below 60%. Room Temperature should be kept above 50F and below 75F. Low humidity and other items such as rugs or carpets around the printer can cause Static electricity which can show as anomalies on your prints. High humidity and high temperatures can cause curling of media or head strikes from the printer.

Contents of ZIP file:

1. Readme File
2. Scanvec Amiable profile with a “.ptf” extension, can be used in either PhotoPRINT or FlexiSIGN-PRO

Intsall Instructions

RIP - FlexiSIGN-PRO 8.0v1 or PhotoPRINT 5.0v1

- Step 1** - If you are using FlexiSIGN-PRO, then the **“Production Manager”** is to be used. If you are using PhotoPRINT then you need not go any further.
- Step 2** - From either application go to **“File”** and then **“Import Preset”**
- Step 3** - In the **“Browser”** dialog box, search for the files that were downloaded of the media chosen.
- Step 4** - These files will have a **“.ptf”** extension to let you know that the profiles belong to a Scanvec Amiable product. Choose and click on **“Open”**. It will now start to Import.
- Step 5** - Once you have chosen your ptf file, it will generate a dialog box to let you know that all was completely successfully. Once this screen appears then click **“OK”**.

How to use the Profile

- Step 1** - Go to **“Setup”** menu and scroll down to **“Default Job Properties”**, then go to the 3rd tab and scroll down the media list to make sure your selection is listed.
- Step 2** - Now that you are assured you media is on the list select any image from the **“Add Job”** menu which can be found by going to the **“File”** menu, then **“Add Job”**.
- Step 3** - Once the job is availble double click on it and go to the 3rd tab or **“Color Management”** tab.
- Step 4** - At the top of this menu you will find the **“Presets”** dropdown menu. Here you can choose your new media. All other items are now set by this preset setting.
- Step 5** - Congratulation you are ready to print.

Handling of Media Recommendations

1. Always make sure you wear gloves as your hand carry oils that release themselves on to the media and may cause the solvent ink not to adhere properly.
2. If you printer is on carpet or a room that is very low in terms of humidity, it is recommended to have an anti-static string, grounding bars or anti-static device to reduce or eliminate static build-up on the material prior to printing.

Please enjoy this and other medias as provided by General Formulations. Thank you.